ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalkunte
Street ID	**Street Name**	**Significant Landmark**
W0134, W0152	NA	NAVY LAYOUT
Segment No.	**Total Length (m)**	
14/S-W0177/S105830	180.0	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	90.0	77.496003	13.003353	77.495730	13.002582	W167	W0131
2	10.0	77.495805	13.003617	77.495899	13.003583	W0170	W0121
3	80.0	77.495770	13.004019	77.495282	13.002477	W0165	DE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to roads at navy lyt	3500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road work	
Tender	**Work Details**	**Job No. / Work Code**
Not Tender	Road work	014-14-000051
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/107/13-14	27/06/2014	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/06/2014	26/09/2014	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9743188999		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ

Zone:DASARAHALLI Ward No:14 Ward Name: Bagalkunte Street ID: ,

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunath
Date of Inspection	**Remarks**	
25/05/2017		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	VIJAY KUMAR	25/05/2017	24/06/2017	COMPLETED
EE	SESHADRI	25/05/2017	24/06/2017	COMPLETED
AEE	SIVA KUMAR	25/05/2017	24/06/2017	COMPLETED
AE	MANJUNATH	25/05/2017	24/06/2017	COMPLETED
AE	MANJUNATH	25/05/2017	24/06/2017	COMPLETED

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalkunte **Street ID:**